

**OSU EHS Department  
Incident Summary**  
For the Period 10/12/09 – 10/18/09

---

311-09	10-12-09	9:05 PM	Kelley
Incident:	Fire Alarm		
Location:	Cordell South		
Details:	Dust activated smoke detector		

---

312-09	10-12-09	11:32 PM	Kelley
Incident:	Fire Alarm		
Location:	Animal Science Bldg.		
Details:	Dust activated smoke detector		

---

313-09	10-14-09	8:18 AM	Fox
Incident:	Odor Investigation		
Location:	Cordell South		
Details:	Natural gas leaking from valves		

---

314-09	10-14-09	8:35 AM	Nutt
Incident:	Ambulance Assist		
Location:	Intersection of Hall of Fame & Western		
Details:	Auto Accident		

---

315-09	10-14-09	11:45 AM	Nutt
Incident:	Fire Alarm		
Location:	Village Apartments, Bldg. D		
Details:	Use of hair dryer activated smoke detector		

---

316-09	10-14-09	7:52	Kelley
Incident:	Ambulance Assist		
Location:	Morrison Apartment Complex		
Details:	Unknown medical condition		

---

317-09	10-14-09	10:04 PM	Kelley
Incident:	Fire Alarm		
Location:	Jones Suites		
Details:	Burned popcorn activated smoke detector		

---

318-09	10-15-09	2:55 PM	Nutt
Incident:	Fire Alarm		
Location:	Davis Apartments		
Details:	Residents using fog machine in apartment		

---

**OSU EHS Department  
Incident Summary**  
For the Period 10/12/09 – 10/18/09

---

319-09	10-15-09	4:00 PM	Kelley
Incident:	Fire Alarm		
Location:	Noble Research Center		
Details:	Use of torch to melt glass near a smoke detector		

---

320-09	10-16-09	10:12 AM	Nutt
Incident:	Fire Alarm		
Location:	Noble Research Center		
Details:	Same glass work activated smoke detector		

---

321-09	10-16-09	2:55 PM	Isaacs
Incident:	Odor Investigation		
Location:	Life Science East		
Details:	No gas odor detected		

---

322-09	10-18-09	3:14 PM	Kelley
Incident:	Fire Alarm		
Location:	Friend Apartments		
Details:	Cooking activated smoke detector		

---

323-09	10-18-09	8:39 PM	Kelley
Incident:	Fire Alarm		
Location:	Village Apartments, Bldg. F		
Details:	Cooking activated smoke detector		

---

324-09	10-18-09	11:23 PM	Kelley
Incident:	Fire Alarm		
Location:	Allen Suites		
Details:	Sparks from faulty wiring in ceiling fan generated smoke that activated alarm system		

---